# **KMXP MR Position Sensor**




- AMR linear position sensor
- 2x6 DFN package, very compact
- Small wall thickness for large air gaps
- High operating temperature of 150°C
- On the edge soldering possible



#### DESCRIPTION

Moving a KMXP sensor along a magnetic scale will produce a sine and a cosine output signal as a function of its position. In order to deliver satisfying results, this will be achieved as long as the air gap between sensor edge and magnetic scale surface does not exceed approximately half of the pole pitch. As the sensor principle is based on the anisotropic magneto resistance effect, the signal amplitudes are nearly independent on the magnetic field strength and therefore air gap variations do not have a strong effect on the accuracy. The sensor detects a magnetic gradient field and is thus almost insensitive to homogenous stray fields.



Precise displacement values will be obtained by using an amplifier in combination with a microcontroller or commercial sine/cosine interpolator device. The maximal obtainable precision depends strongly on the accuracy of the magnetic scale and on the distance sensor – magnetic scale. Precision values of <1% of the pole pitch are common.

#### **FEATURES**

- Contactless angular position measurement
- High accuracy
- Low cost, low power
- Failure detection possible
- User has total control over signal evaluation
- Extended temperature range
- REACH, 3TG & ROHS compliant

#### APPLICATIONS

- Measurement of linear displacements, movements, velocities in dirty environments
- Very precise angular measurement on the circumference using pole wheels
- Torque measurement in harsh environment

#### **PERFORMANCE SPECS**

PARAMETER	SYMBOL	COND.	Түре	ΜιΝ	Түр	MAX	Unit
1. Operating Limits							
max. supply voltage	V <sub>cc,max</sub>		all			10	V
max. current (both bridges)	I <sub>cc,max</sub>		KMXP 1000 KMXP 2000/5000			5 10	mA
operating temperature	T <sub>op</sub>		all	-40		+150	°C
storage temperature	T <sub>st</sub>		all	-40		+125	°C
2. Sensor Specifications (	T=25 °C)						
Supply voltage	V <sub>cc</sub>		all		5		V
pole pitch 1)	р		KMXP 1000 KMXP 2000 KMXP 5000		1000 2000 5000		μm
Air gap package front – magnetic scale 2)	D		KMXP 1000 KMXP 2000 KMXP 5000	0.1 0.2 0.5	0.4 0.8 2	0.8 1.8 4	mm
Resistance (both bridges)	R <sub>b</sub>		KMXP 1000 KMXP 2000/5000	2000 1000	3000 1500	4000 2000	Ω
Output signal range	$\Delta V_n / V_{cc}$	А, В	all	18	22	26	mV/V
Offset voltage	V <sub>n off</sub>	А, В	all	-1	0	+1	mV/V
3. Sensor Specifications							•
TC of amplitude	TCSV	A, C	All		-0.35		%/K
TC of resistance	TCBR	A, C	All		+0.35		%/K
TC of offset	TCVoff	A, C	all	-4	0	+4	μV/V/K

n = 1;2 (bridge number); Stress above one or more of the limiting values may cause permanent damage to the device. Exposure to limiting values for extended periods may affect device reliability.

1) Other pole pitches on request

2) Typical values for conventional magnetic scales. Air gap for maximum accuracy depends on the used scale.

#### **MEASUREMENT SET UP CONDITIONS**

PARAMETER	SYMBOL	UNIT	CONDITION
A. Set Up Conditions			
ambient temperature	Т	°C	T = 25 °C (unless otherwise noted)
supply voltage	V <sub>cc</sub>	V	Vcc = 5 V
applied magnetic field	Н	kA/m	H > 10 kA/m
B. Sensor Specifications (T=25	°C, 360° turn	, H=25 kA/m	, Vo <sub>max</sub> >0, Vo <sub>min</sub> <0)
output signal range	$\Delta V_n / V_{cc}$	mV/V	$\Delta V_n / V_{cc} = (V_n _{max} - V_n _{min}) / V_{cc}$
signal offset	V <sub>off n</sub>	mV/V	$V_{off n} = (V_{n max} + V_{n min}) / V_{cc}$
C. Sensor Specifications (T=-25	°C, +125°C)		
ambient temperatures	Т	°C	T <sub>1</sub> = -25 °C, T <sub>0</sub> = +25 °C, T <sub>2</sub> = +125 °C
TC of amplitude	TCSV	%/K	$TCV = \frac{1}{(T_2 - T_1)} \cdot \frac{\frac{\Delta V_n}{V_{cc}}(T_2) - \frac{\Delta V_n}{V_{cc}}(T_1)}{\frac{\Delta V_n}{V_{cc}}(T_1)} \cdot 100\%$
TC of resistance	TCBR	%/K	$TCR = \frac{1}{(T_2 - T_1)} \cdot \frac{R_n(T_2) - R_n(T_1)}{R_n(T_1)} \cdot 100\%$
TC of offset	TCVoff	μV/(VK)	$TCVoff_n = \frac{Voff_n(T_2) - Voff_n(T_1)}{(T_2 - T_1)}$

n = 1;2 (bridge number)

### **BLOCK DIAGRAM**




Figure 1a: KMXP 1000/2000




Figure 1b: KMXP 5000

#### **TYPICAL PERFORMANCE CURVES**





Figure 2: typical output signal voltage depending on sensor position

### **FUNCTION**




pole-length

Figure 3: principle function of the sensor

The KMXP sensors consists of two magneto resistive Wheatstone bridges, whose resistors are placed in a way that the characteristic magnetic field distribution of a magnetic scale with matching pole pitch produces a sine and a cosine signal output, when the sensor is moved along the scale. In addition, some sensor types integrate over more than one pole in order to improve sensor performance.

#### EXAMPLE FOR A PRINTED CIRCUIT BOARD ASSEMBLY




### **PIN ASSIGNMENT**

The pin assignment is pin compatible for all KMXP types and allows a common PCB layout for all types:

Pin	1	2	3	4	5	6	7	8	9	10	11	12
KMXP5000	Vcc2	-V2	-V1	GND	Vcc1	+V1	+V2	N/C	N/C	N/C	N/C	N/C
KMXP2000	N/C	-V2	-V1	GND	Vcc	+V1	+V2	N/C	N/C	N/C	N/C	N/C
KMXP1000	N/C	-V2	-V1	GND	Vcc	+V1	+V2	N/C	N/C	N/C	N/C	N/C

# **KMXP Magneto Resistive Position Sensor**

## PHYSICAL DIMENSIONS






Fig. 4: Physical dimensions of sensor package

Reflow profile for this package according to IPC/JEDEC J-STD-020 Revision D.1 (March 2008).

#### APPLICATION EXAMPLE




Fig. 5: Exemplary hardware configuration for the usage with a conventional microcontroller using an Analog Devices AD8605 amplifier for the preprocessing of the sensor signals.

# **KMXP Magneto Resistive Position Sensor**

KMXP 1000	KMXP 2000	KMXP 5000	
1 mm	2 mm	5 mm	

The information in this sheet has been carefully reviewed and is believed to be accurate; however, no responsibility is assumed for inaccuracies. Furthermore, this information does not convey to the purchaser of such devices any license under the patent rights to the manufacturer. Measurement Specialties, Inc. reserves the right to make changes without further notice to any product herein. Measurement Specialties, Inc. makes no warranty, representation or guarantee regarding the suitability of its product for any particular purpose, nor does Measurement Specialties, Inc. assume any liability arising out of the application or use of any product or circuit and specifically disclaims any and all liability, including without limitation consequential or incidental damages. Typical parameters can and do vary in different applications. All operating parameters must be validated for each customer application by customer's technical experts. Measurement Specialties, Inc. does not convey any license under its patent rights nor the rights of others.